

SIGMA ENGINEERING

P.J. & D.M. LANDER

25 BRICKFIELD ESTATE, GILLINGHAM, DORSET SP8 4JL

VAT Registration No. 186 3058 48

AUTOMOTIVE SPECIALISTS

Mr. Giles

Tax Point 19

Date of Invoice 7. 5. 1994

Quantity	Description	Amount Exclusive of VAT	
	<u>Fraser Nash</u>		
2	Needles	6	70
	Setup car on 'Rolling Road' - check timing & advance mechanism. Reset advance retard cable bracket. Turn engine, check mixture, power output. Change carburettor needles.	65	00
	Too high top gear? - for engine characteristics.		
	Advance retard mechanism must start from full retard (lever to be up on mag) 27°, then operate approx. half advance 33-35°.		
		TOTAL	71 70
		VAT	12 54
		TOTAL incl. VAT	84 24

Paid with thanks